



Waveform comparison



FCMA Soft Starters control the amplitude of Motor current without distorting the current waveform. This leads to zero harmonics and substantially low starting current.

FCMA – Flux compensated magnetic amplifier

Acceleration Curves



Model SC1 connection
Soft starter module

